



DEPARTMENT OF
WATER RESOURCES

CACHE CREEK AREA *Fact Sheet* **Site 0.8**

Critical Levee Erosion Site

Emergency Levee Repairs

Location

River: Cache Creek

Levee Mile: 0.8

Latitude/Longitude:

38.716989/-121.815449

Nearest Impact Area:

Woodland

County: Yolo

Bank: Left

Type of Damage

Bank erosion

Length of Repair

965 feet (approximate)

Repair Type

Setback levee

Lead Agency

Department of Water Resources

For further information,
please contact:

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov

